

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
1278 ALPINE CT	P	N	P	Installed after lead ban	N	Field inspection only	Y
921 BEECH ST	C	N	C	Installation record	N	Field inspection only	Y
931 BEECH ST	C	N	C	Installation record	N	Field inspection only	Y
941 BEECH ST	C	N	C	Installation record	N	Field inspection only	Y
1104 BEECH ST	P	N	C	Installation record	Y	Field inspection only	Y
1125 BEECH ST	P	N	C	Installation record	Y	Field inspection only	Y
1130 BEECH ST	P	N	C	Installation record	Y	Field inspection only	Y
1030 BEECH ST	C	N	UNK-LG	Installation record	N	Other - describe in notes	N
1032 BEECH ST	C	N	UNK-LG	Installation record	N	Other - describe in notes	N
200 BEECHWOOD ST	P	N	P	Field inspection only	Y	Field inspection only	Y
201 BEECHWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
202 BEECHWOOD ST	UNK-LG	N	P	Other - describe in notes	N	Field inspection only	Y
203 BEECHWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
205 BEECHWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
206 BEECHWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
207 BEECHWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
208 BEECHWOOD ST	UNK-LG	N	P	Other - describe in notes	N	Field inspection only	Y
209 BEECHWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
210 BEECHWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
211 BEECHWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
212 BEECHWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
213 BEECHWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
215 BEECHWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
301 BEECHWOOD ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
302 BEECHWOOD ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
303 BEECHWOOD ST	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
304 BEECHWOOD ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
305 BEECHWOOD ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
306 BEECHWOOD ST	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
307 BEECHWOOD ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
308 BEECHWOOD ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
309 BEECHWOOD ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
310 BEECHWOOD ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
311 BEECHWOOD ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
312 BEECHWOOD ST	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
313 BEECHWOOD ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
314 BEECHWOOD ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
315 BEECHWOOD ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
909 BIRCH ST	P	N	C	Installation record	Y	Field inspection only	Y
939 BIRCH ST	C	N	C	Installation record	N	Field inspection only	Y
1011 BIRCH ST	P	N	C	Installation record	Y	Field inspection only	Y
805 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
810 CENTER ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
823 CENTER ST	UNK-LG	N	P	Other - describe in notes	N	Field inspection only	Y
860 CENTER ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
865 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
891 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
894 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
901 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
907 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
916 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
917 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
927 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
929 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
934 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
939 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
946 CENTER ST	P	N	P	Installed after lead ban	N	Field inspection only	Y
1020 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1028 CENTER ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1188 CENTER ST	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
907 CHERRY HILL DR	P	N	C	Installation record	Y	Field inspection only	Y
917 CHERRY HILL DR	P	N	C	Installation record	Y	Field inspection only	Y
920 CHERRY HILL DR	P	N	C	Installation record	Y	Field inspection only	Y
927 CHERRY HILL DR	P	N	C	Installation record	Y	Field inspection only	Y
930 CHERRY HILL DR	P	N	C	Installation record	Y	Field inspection only	Y
937 CHERRY HILL DR	P	N	C	Installation record	Y	Field inspection only	Y
940 CHERRY HILL DR	P	N	C	Installation record	Y	Field inspection only	Y
899 CITRUS LN	C	N	C	Installation record	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
908 CITRUS LN	P	N	C	Installation record	Y	Field inspection only	Y
909 CITRUS LN	P	N	C	Installation record	Y	Field inspection only	Y
916 CITRUS LN	P	N	C	Installation record	Y	Field inspection only	Y
924 CITRUS LN	P	N	C	Installation record	Y	Field inspection only	Y
929 CITRUS LN	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
934 CITRUS LN	P	N	C	Installation record	Y	Field inspection only	Y
943 CITRUS LN	C	N	C	Installation record	N	Field inspection only	Y
944 CITRUS LN	C	N	C	Installation record	N	Field inspection only	Y
901 DAIRYLAND DR	C	N	C	Installed after lead ban	N	Field inspection only	Y
1271 DAIRYLAND DR	P	N	P	Field inspection only	Y	Field inspection only	Y
1421 DAIRYLAND DR	P	N	P	Installation record	Y	Field inspection only	Y
912 DELTA CT	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
915 DELTA CT	UNK-LG	N	C	Other - describe in notes	N	Installed after lead ban	Y
928 DELTA CT	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
931 DELTA CT	UNK-LG	N	P	Other - describe in notes	N	Field inspection only	Y
944 DELTA CT	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
947 DELTA CT	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
822 DELTA ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
838 DELTA ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
854 DELTA ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
870 DELTA ST	UNK-LG	N	P	Other - describe in notes	N	Field inspection only	Y
875 DELTA ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
919 E GRANT AVE	C	N	C	Installation record	N	Field inspection only	Y
945 E GRANT AVE	C	N	C	Installed after lead ban	N	Field inspection only	Y
336 E JEFFERSON AVE	P	N	C	Installation record	Y	Field inspection only	Y
337 E JEFFERSON AVE	P	N	C	Installation record	Y	Field inspection only	Y
348 E JEFFERSON AVE	P	N	C	Installation record	Y	Field inspection only	Y
358 E JEFFERSON AVE	P	N	C	Installation record	Y	Field inspection only	Y
368 E JEFFERSON AVE	P	N	C	Installation record	Y	Field inspection only	Y
629 E JEFFERSON AVE	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
653 E JEFFERSON AVE	UNK-NOLG	N	C	Installation record	N	Field inspection only	Y
658 E JEFFERSON AVE	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
662 E JEFFERSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
663 E JEFFERSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
664 E JEFFERSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
673 E JEFFERSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
674 E JEFFERSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
682 E JEFFERSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
687 E JEFFERSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
692 E JEFFERSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
699 E JEFFERSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
856 E MADISON AVE	C	N	C	Installation record	N	Field inspection only	Y
910 E MADISON AVE	C	N	C	Installation record	N	Field inspection only	Y
913 E MADISON AVE	C	N	C	Installation record	N	Field inspection only	Y
918 E MADISON AVE	C	N	C	Installation record	N	Field inspection only	Y
919 E MADISON AVE	C	N	C	Installation record	N	Field inspection only	Y
245 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
260 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
310 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
311 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
324 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
331 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
334 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
347 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
350 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
353 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
361 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
370 E WASHINGTON AVE	C	N	C	Installed after lead ban	N	Field inspection only	Y
375 E WASHINGTON AVE	C	N	C	SL repair/replace record	Y	Field inspection only	Y
379 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
382 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
411 E WASHINGTON AVE	DI	N	DI	Diameter > 2 inches	N	Field inspection only	Y
531 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
541 E WASHINGTON AVE	P	N	C	Installation record	Y	Field inspection only	Y
605 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
615 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
657 E WASHINGTON AVE	C	N	P	Installation record	N	Field inspection only	Y
665 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
675 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
685 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
695 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
719 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
727 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
729 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
733 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
751 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
762 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
767 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
810 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
811 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
814 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
823 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
848 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
920 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
944 E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
908A E WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
100 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
101 EDGEWOOD ST	UNK-LG	N	P	Other - describe in notes	N	Field inspection only	Y
102 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
103 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
104 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
105 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
106 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
107 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
108 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
109 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
110 EDGEWOOD ST	UNK-LG	N	P	Other - describe in notes	N	Field inspection only	Y
111 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
112 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
113 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
114 EDGEWOOD ST	UNK-LG	N	G	Other - describe in notes	N	Field inspection only	Y
115 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
116 EDGEWOOD ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
118 EDGEWOOD ST	UNK-LG	N	P	Other - describe in notes	N	Field inspection only	Y
1011 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1015 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1020 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1023 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1030 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1039 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1040 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1047 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1055 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1101 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1104 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1105 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1109 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1140 ELM ST	C	N	C	Installation record	N	Field inspection only	Y
1107 END CT	C	N	C	Installation record	N	Field inspection only	Y
1141 FRANKLIN DR	C	N	C	Installation record	N	Field inspection only	Y
1151 FRANKLIN DR	C	N	C	Installation record	N	Field inspection only	Y
1160 FRANKLIN DR	C	N	C	Installation record	N	Field inspection only	Y
1176 FRANKLIN DR	C	N	C	Installation record	N	Field inspection only	Y
1181 FRANKLIN DR	C	N	C	Installation record	N	Field inspection only	Y
1184 FRANKLIN DR	C	N	C	Installation record	N	Field inspection only	Y
1202 FRANKLIN DR	C	N	C	Installation record	N	Field inspection only	Y
1211 FRANKLIN DR	C	N	C	Installation record	N	Field inspection only	Y
1220 FRANKLIN DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1221 FRANKLIN DR	C	N	C	Previous eval	Y	Field inspection only	Y
1232 FRANKLIN DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1233 FRANKLIN DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1245 FRANKLIN DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1247 FRANKLIN DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1250 FRANKLIN DR	UNK-LG	N	P	Other - describe in notes	N	Field inspection only	Y
1255 FRANKLIN DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1265 FRANKLIN DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
1270 FRANKLIN DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1275 FRANKLIN DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1278 FRANKLIN DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1284 FRANKLIN DR	C	N	C	Installation record	N	Field inspection only	Y
1287 FRANKLIN DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1290 FRANKLIN DR	C	N	C	Installation record	N	Field inspection only	Y
1296 FRANKLIN DR	C	N	C	Installation record	N	Field inspection only	Y
1297 FRANKLIN DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1299 FRANKLIN DR	C	N	C	Field inspection only	Y	Field inspection only	Y
1009 HAZEL ST	C	N	C	Installation record	N	Field inspection only	Y
1013 HAZEL ST	C	N	C	Installation record	N	Field inspection only	Y
1021 HAZEL ST	C	N	C	Installation record	N	Field inspection only	Y
1043 HAZEL ST	C	N	C	Installation record	N	Other - describe in notes	Y
1053 HAZEL ST	C	N	C	Field inspection only	Y	Field inspection only	Y
1061 HAZEL ST	C	N	C	Installation record	N	Field inspection only	Y
1105 HAZEL ST	C	N	C	Installation record	N	Field inspection only	Y
1117 HAZEL ST	C	N	C	Installation record	N	Field inspection only	Y
1123 HAZEL ST	C	N	C	Installation record	N	Field inspection only	Y
1127 HAZEL ST	C	N	C	Installation record	N	Field inspection only	Y
1139 HAZEL ST	C	N	C	Installation record	N	Field inspection only	Y
1219 HAZEL ST	C	N	C	Installation record	N	Field inspection only	Y
1223 HAZEL ST	C	N	C	Installation record	N	Field inspection only	Y
1231 HAZEL ST	C	N	C	Installation record	N	Field inspection only	Y
1053A HAZEL ST	C	N	C	Field inspection only	Y	Field inspection only	Y
1024 HEMLOCK ST	C	N	C	Installation record	N	Field inspection only	Y
1029 HEMLOCK ST	C	N	C	Installation record	N	Field inspection only	Y
1056 HEMLOCK ST	C	N	UNK-LG	Installation record	N	Other - describe in notes	N
855 HICKORY ST	UNK-NOLG	N	P	Other - describe in notes	N	Field inspection only	Y
871 HICKORY ST	C	N	C	Installation record	N	Field inspection only	Y
872 HICKORY ST	C	N	C	Installation record	N	Field inspection only	Y
876 HICKORY ST	P	N	C	Installation record	Y	Field inspection only	Y
904 HICKORY ST	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
911 HICKORY ST	C	N	C	Installation record	N	Field inspection only	Y
918 HICKORY ST	C	N	C	Installation record	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
921 HICKORY ST	C	N	C	Installation record	N	Field inspection only	Y
1024 HICKORY ST	C	N	C	Installation record	N	Field inspection only	Y
1044 HICKORY ST	C	N	C	Installation record	N	Field inspection only	Y
1060 HICKORY ST	C	N	C	Installation record	N	Field inspection only	Y
1202 HICKORY ST	C	N	C	Installation record	N	Field inspection only	Y
1210 HICKORY ST	C	N	C	Installation record	N	Field inspection only	Y
1220 HICKORY ST	C	N	C	Installation record	N	Field inspection only	Y
1238 HICKORY ST	C	N	P	Installation record	N	Field inspection only	Y
1270 HICKORY ST	C	N	C	Installation record	N	Field inspection only	Y
855 HICKORY GARAGE	C	N	C	Installation record	N	Other - describe in notes	N
795 JACKSON DR	UNK-LG	N	C	Water sampling only	N	Field inspection only	Y
807 JACKSON DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
815 JACKSON DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
822 JACKSON DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
835 JACKSON DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
869 JACKSON DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
901 JACKSON DR	UNK-LG	N	C	Installation record	N	Field inspection only	Y
911 JACKSON DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
920 JACKSON DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
921 JACKSON DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1409 JACKSON DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1412 JACKSON DR	UNK-LG	N	C	Installation record	N	Field inspection only	Y
1423 JACKSON DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1435 JACKSON DR	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1438 JACKSON DR	UNK-LG	N	C	Installation record	N	Field inspection only	Y
1011 JUNIPER ST	C	N	C	Installation record	N	Field inspection only	Y
1015 JUNIPER ST	C	N	C	Installation record	N	Field inspection only	Y
1018 JUNIPER ST	C	N	C	Installation record	N	Field inspection only	Y
1019 JUNIPER ST	C	N	C	Installation record	N	Field inspection only	Y
1024 JUNIPER ST	C	N	C	Installation record	N	Field inspection only	Y
1040 JUNIPER ST	C	N	C	Installation record	N	Field inspection only	Y
1050 JUNIPER ST	C	N	C	Installation record	N	Field inspection only	Y
1060 JUNIPER ST	C	N	C	Installation record	N	Field inspection only	Y
1327 JUNIPER ST	P	N	P	Installation record	Y	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
1203 LAKE BLUFF CT	C	N	C	Installed after lead ban	N	Field inspection only	Y
1209 LAKE BLUFF CT	C	N	C	Installed after lead ban	N	Field inspection only	Y
1215 LAKE BLUFF CT	C	N	C	Installed after lead ban	N	Field inspection only	Y
1218 LAKE BLUFF CT	C	N	P	Field inspection only	Y	Field inspection only	Y
1222 LAKE BLUFF CT	C	N	C	Installed after lead ban	N	Field inspection only	Y
1227 LAKE BLUFF CT	C	N	C	Installed after lead ban	N	Field inspection only	Y
1234 LAKE BLUFF CT	C	N	C	Installed after lead ban	N	Field inspection only	Y
1235 LAKE BLUFF CT	C	N	C	Installed after lead ban	N	Field inspection only	Y
1246 LAKE BLUFF CT	C	N	P	Installed after lead ban	N	Field inspection only	Y
1251 LAKE BLUFF CT	C	N	C	Installed after lead ban	N	Field inspection only	Y
1258 LAKE BLUFF CT	C	N	C	Installed after lead ban	N	Field inspection only	Y
1262 LAKE BLUFF CT	C	N	C	Installed after lead ban	N	Field inspection only	Y
1265 LAKE BLUFF CT	C	N	P	Installed after lead ban	N	Field inspection only	Y
870 LAKESHORE DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
936 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
979 LAKESHORE DR	C	N	P	Field inspection only	Y	Field inspection only	Y
1007 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1015 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1033 LAKESHORE DR	P	N	P	Installed after lead ban	Y	Field inspection only	Y
1041 LAKESHORE DR	C	N	DNE	Field inspection only	Y	Other - describe in notes	N
1121 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1148 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1151 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1151 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1231 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1241 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1251 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1261 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1263 LAKESHORE DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1290 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1298 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1309 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1313 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1325 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
1337 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1341 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1349 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1367 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1391 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1411 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1461 LAKESHORE DR	C	N	C	Installed after lead ban	N	Field inspection only	Y
1463 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1471 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1481 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1489 LAKESHORE DR	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
1507 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1521 LAKESHORE DR	C	N	C	Installation record	N	Field inspection only	Y
1551 LAKESHORE DR	C	N	P	Installation record	N	Field inspection only	Y
1611 LAKESHORE DR	P	N	C	Installation record	Y	Field inspection only	Y
1677 LAKESHORE DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1691 LAKESHORE DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1705 LAKESHORE DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1717 LAKESHORE DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1725 LAKESHORE DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1747 LAKESHORE DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1789 LAKESHORE DR	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
1801 LAKESHORE DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
105 LINCOLN AVE	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
110 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
204 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
214 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
215 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
220 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
223 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
247 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
252 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
253 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
261 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
265 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
315 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
316 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
330 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
331 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
340 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
346 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
349 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
360 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
371 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
380 LINCOLN AVE	C	N	C	Installation record	N	Field inspection only	Y
381 LINCOLN AVE	P	N	C	Installation record	Y	Field inspection only	Y
782 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
803 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
805 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
808 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
809 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
810 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
813 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
851 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
858 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
861 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
871 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
874 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
904 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
905 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
914 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
919 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
920 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
930 LINDEN ST	P	N	C	Installation record	Y	Field inspection only	Y
1050 LINDEN ST	C	N	C	Installation record	N	Field inspection only	Y
1051 LINDEN ST	UNK-NOLG	N	UNK-NOLG	Installed after lead ban	N	Installed after lead ban	N
1105 LINDEN ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
1107 LINDEN ST	C	N	C	Installed after lead ban	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
1117 LINDEN ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
1119 LINDEN ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
1127 LINDEN ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
1129 LINDEN ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
1141 LINDEN ST	C	N	P	Installed after lead ban	N	Field inspection only	Y
1143 LINDEN ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
1145 LINDEN ST	C	N	P	Installed after lead ban	N	Field inspection only	Y
1147 LINDEN ST	C	N	P	Installed after lead ban	N	Field inspection only	Y
841 MAPLE ST	P	N	C	Installation record	Y	Field inspection only	Y
848 MAPLE ST	P	N	P	Installation record	Y	Field inspection only	Y
853 MAPLE ST	P	N	C	Installation record	Y	Field inspection only	Y
858 MAPLE ST	P	N	C	Installation record	Y	Field inspection only	Y
869 MAPLE ST	P	N	C	Installation record	Y	Field inspection only	Y
870 MAPLE ST	P	N	C	Installation record	Y	Field inspection only	Y
901 MAPLE ST	P	N	C	Installation record	Y	Field inspection only	Y
907 MAPLE ST	P	N	C	Installation record	Y	Field inspection only	Y
1120 MAPLE ST	C	N	P	Installed after lead ban	N	Field inspection only	Y
1132 MAPLE ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
1141 MAPLE ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
1315 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1316 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1322 MARSHALL AVE	C	N	C	Field inspection only	Y	Field inspection only	Y
1330 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1331 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1338 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1345 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1346 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1354 MARSHALL AVE	C	N	DNE	Field inspection only	Y	Other - describe in notes	N
1400 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1419 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1429 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1430 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1439 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1440 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
1445 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1446 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1454 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1455 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1460 MARSHALL AVE	C	N	C	Installation record	N	Field inspection only	Y
1204 MEADOWBROOK CT	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1207 MEADOWBROOK CT	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1216 MEADOWBROOK CT	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1219 MEADOWBROOK CT	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1228 MEADOWBROOK CT	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
1231 MEADOWBROOK CT	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1240 MEADOWBROOK CT	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1243 MEADOWBROOK CT	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1252 MEADOWBROOK CT	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
1255 MEADOWBROOK CT	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1267 MEADOWBROOK CT	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
1230 MEADOWBROOK DR	P	N	P	Installed after lead ban	N	Field inspection only	Y
1231 MEADOWBROOK DR	P	N	P	Installed after lead ban	N	Field inspection only	Y
1232 MEADOWBROOK DR	P	N	P	Installed after lead ban	N	Field inspection only	Y
1233 MEADOWBROOK DR	P	N	P	Installed after lead ban	N	Field inspection only	Y
1234 MEADOWBROOK DR	P	N	P	Installed after lead ban	N	Field inspection only	Y
1235 MEADOWBROOK DR	P	N	P	Installed after lead ban	N	Field inspection only	Y
1236 MEADOWBROOK DR	P	N	P	Installed after lead ban	N	Field inspection only	Y
1237 MEADOWBROOK DR	P	N	P	Installed after lead ban	N	Field inspection only	Y
1238 MEADOWBROOK DR	P	N	P	Installed after lead ban	N	Field inspection only	Y
1239 MEADOWBROOK DR	P	N	P	Installed after lead ban	N	Field inspection only	Y
1240 MEADOWBROOK DR	P	N	P	Installed after lead ban	N	Field inspection only	Y
1241 MEADOWBROOK DR	P	N	P	Installed after lead ban	N	Field inspection only	Y
1270 MEADOWBROOK DR 1	P	N	P	Installed after lead ban	N	Field inspection only	Y
1270 MEADOWBROOK DR 2	P	N	P	Installed after lead ban	N	Field inspection only	Y
1270 MEADOWBROOK DR 3	P	N	P	Installed after lead ban	N	Field inspection only	Y
1270 MEADOWBROOK DR 4	P	N	P	Installed after lead ban	N	Field inspection only	Y
1270 MEADOWBROOK DR 5	P	N	P	Installed after lead ban	N	Field inspection only	Y
1270 MEADOWBROOK DR 6	P	N	P	Installed after lead ban	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
1270 MEADOWBROOK DR 7	P	N	P	Installed after lead ban	N	Field inspection only	Y
1270 MEADOWBROOK DR 8	P	N	P	Installed after lead ban	N	Field inspection only	Y
1270 MEADOWBROOK DR Fauc	P	N	P	Installed after lead ban	N	Field inspection only	Y
1272 MEADOWBROOK DR 1	P	N	C	SL repair/replace record	Y	Field inspection only	Y
1272 MEADOWBROOK DR 2	P	N	C	SL repair/replace record	Y	Field inspection only	Y
1274 MEADOWBROOK DR 1	P	N	C	Installed after lead ban	N	Field inspection only	Y
1274 MEADOWBROOK DR 2	P	N	C	Installed after lead ban	N	Field inspection only	Y
1276 MEADOWBROOK DR 1	P	N	P	Installed after lead ban	N	Field inspection only	Y
1276 MEADOWBROOK DR 2	P	N	P	Installed after lead ban	N	Field inspection only	Y
1278 MEADOWBROOK DR 1	P	N	P	Installed after lead ban	N	Field inspection only	Y
1278 MEADOWBROOK DR 2	P	N	P	Installed after lead ban	N	Field inspection only	Y
1323 MEADOWBROOK DR	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
1386 MEADOWBROOK DR	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
1402 MEADOWBROOK DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1411 MEADOWBROOK DR	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
1414 MEADOWBROOK DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1421 MEADOWBROOK DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1426 MEADOWBROOK DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1433 MEADOWBROOK DR	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
1438 MEADOWBROOK DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1445 MEADOWBROOK DR	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1450 MEADOWBROOK DR	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
1077 N MAPLE ST	UNK-NOLG	N	DNE	Installed after lead ban	N	Other - describe in notes	N
1013 N WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
1018 N WESTVIEW ST	P	N	C	Field inspection only	Y	Field inspection only	Y
1221 N WESTVIEW ST	UNK-NOLG	N	P	Installed after lead ban	N	Field inspection only	Y
1224 N WESTVIEW ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
1229 N WESTVIEW ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
1236 N WESTVIEW ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
1248 N WESTVIEW ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
1272 N WESTVIEW ST	C	N	C	Field inspection only	Y	Field inspection only	Y
1279 N WESTVIEW ST	C	N	C	Field inspection only	Y	Field inspection only	Y
326 NORTH AVE	C	N	C	Installation record	N	Field inspection only	Y
1025 NORTH AVE	P	N	P	Installed after lead ban	Y	Installed after lead ban	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
1025 NORTH AVE	P	N	P	Installed after lead ban	Y	Installed after lead ban	Y
1205 NORTH AVE	C	N	C	Installation record	N	Field inspection only	Y
1213 NORTH AVE	P	N	P	Field inspection only	Y	Field inspection only	Y
1290 NORTH AVE	P	N	DI	Installation record	Y	Installation record	Y
1290 NORTH AVE	P	N	DI	Installation record	Y	Installation record	Y
1290 NORTH AVE	P	N	DI	Installation record	Y	Installation record	Y
1290 NORTH AVE	P	N	DI	Installation record	Y	Installation record	Y
1290 NORTH AVE	P	N	DI	Installation record	Y	Installation record	Y
1290 NORTH AVE	P	N	DI	Installation record	Y	Installation record	Y
1290 NORTH AVE	P	N	DI	Installation record	Y	Installation record	Y
1290 NORTH AVE	P	N	DI	Installation record	Y	Installation record	Y
1290 NORTH AVE	P	N	DI	Installation record	Y	Installation record	Y
1290 NORTH AVE	P	N	DI	Installation record	Y	Installation record	Y
1290 NORTH AVE	P	N	DI	Installation record	Y	Installation record	Y
1290 NORTH AVE	P	N	DI	Installation record	Y	Installation record	Y
1486 NORTH AVE	P	N	C	Installation record	Y	Field inspection only	Y
1517 NORTH AVE	P	N	C	Installation record	Y	Field inspection only	Y
1519 NORTH AVE	P	N	C	Installation record	Y	Field inspection only	Y
1520 NORTH AVE	P	N	C	Installation record	Y	Field inspection only	Y
1532 NORTH AVE	P	N	C	Installation record	Y	Field inspection only	Y
1544 NORTH AVE	P	N	C	Installation record	Y	Field inspection only	Y
1020 OAK ST	C	N	C	Installation record	N	Field inspection only	Y
1021 OAK ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1035 OAK ST	C	N	C	Installation record	N	Field inspection only	Y
1136 PARK CT	UNK-LG	N	C	Installation record	N	Field inspection only	Y
1144 PARK CT	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1145 PARK CT	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1221 PARK LN	C	N	C	Installation record	N	Field inspection only	Y
1245 PARK LN	C	N	C	Installation record	N	Field inspection only	Y
100 PARKWAY ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
101 PARKWAY ST	UNK-LG	N	p	Other - describe in notes	N	Field inspection only	Y
102 PARKWAY ST	UNK-LG	N	p	Other - describe in notes	N	Field inspection only	Y
103 PARKWAY ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
104 PARKWAY ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
105 PARKWAY ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
106 PARKWAY ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
107 PARKWAY ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
108 PARKWAY ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
109 PARKWAY ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
110 PARKWAY ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
111 PARKWAY ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
112 PARKWAY ST	C	N	P	Field inspection only	Y	Field inspection only	Y
113 PARKWAY ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
114 PARKWAY ST	UNK-LG	N	P	Other - describe in notes	N	Field inspection only	Y
115 PARKWAY ST	UNK-LG	N	P	Other - describe in notes	N	Field inspection only	Y
117 PARKWAY ST	UNK-LG	N	P	Other - describe in notes	N	Field inspection only	Y
860 POLK LN	C	N	C	Installation record	N	Field inspection only	Y
903 POLK LN	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
904 POLK LN	C	N	C	Installation record	N	Field inspection only	Y
924 POLK LN	C	N	C	Installation record	N	Field inspection only	Y
940 POLK LN	C	N	C	Installation record	N	Field inspection only	Y
940 POLK LN - back lot on Westview	C	N	DNE	Installation record	N	Other - describe in notes	N
1016 W GRANT AVE	C	N	C	Installation record	N	Field inspection only	Y
1034 W GRANT AVE	C	N	C	Installation record	N	Field inspection only	Y
1042 W GRANT AVE	C	N	C	Installation record	N	Field inspection only	Y
1047 W GRANT AVE	C	N	C	Installation record	N	Field inspection only	Y
1048 W GRANT AVE	C	N	C	Installation record	N	Field inspection only	Y
1052 W GRANT AVE	C	N	C	Installation record	N	Field inspection only	Y
1056 W GRANT AVE	C	N	C	Installation record	N	Field inspection only	Y
1120 W JEFFERSON AVE	C	N	C	Field inspection only	Y	Field inspection only	Y
1130 W JEFFERSON AVE	C	N	C	Field inspection only	Y	Field inspection only	Y
1135 W JEFFERSON AVE	C	N	C	Field inspection only	Y	Field inspection only	Y
1140 W JEFFERSON AVE	C	N	C	Field inspection only	Y	Field inspection only	Y
1141 W JEFFERSON AVE	C	N	C	Field inspection only	Y	Field inspection only	Y
1146 W JEFFERSON AVE	C	N	C	Field inspection only	Y	Field inspection only	Y
1147 W JEFFERSON AVE	C	N	C	Field inspection only	Y	Field inspection only	Y
1016 W MADISON AVE	C	N	C	Installation record	N	Field inspection only	Y
1140 W MADISON AVE	C	N	C	Installation record	N	Field inspection only	Y
1149 W MADISON AVE	C	N	C	Installation record	N	Field inspection only	Y
1155 W MADISON AVE	C	N	C	Installed after lead ban	N	Field inspection only	Y
1157 W MADISON AVE	C	N	C	Installed after lead ban	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
1158 W MADISON AVE	C	N	C	Installation record	N	Field inspection only	Y
1160 W MADISON AVE	C	N	P	Field inspection only	Y	Field inspection only	Y
1164 W MADISON AVE	C	N	P	Field inspection only	Y	Field inspection only	Y
1167 W MADISON AVE 1	C	N	C	Installed after lead ban	N	Field inspection only	Y
1167 W MADISON AVE 2	C	N	C	Installed after lead ban	N	Field inspection only	Y
1167 W MADISON AVE 3	C	N	C	Installed after lead ban	N	Field inspection only	Y
1167 W MADISON AVE 4	C	N	C	Installed after lead ban	N	Field inspection only	Y
1167 W MADISON AVE 5	C	N	C	Installed after lead ban	N	Field inspection only	Y
1167 W MADISON AVE 6	C	N	C	Installed after lead ban	N	Field inspection only	Y
1170 W MADISON AVE	P	N	DNE	Field inspection only	Y	Other - describe in notes	N
1180 W MADISON AVE	C	N	DNE	Installed after lead ban	N	Other - describe in notes	N
1191 W MADISON AVE 1	C	N	C	Installed after lead ban	N	Field inspection only	Y
1191 W MADISON AVE 2	C	N	C	Installed after lead ban	N	Field inspection only	Y
1191 W MADISON AVE 3	C	N	C	Installed after lead ban	N	Field inspection only	Y
1191 W MADISON AVE 4	C	N	C	Installed after lead ban	N	Field inspection only	Y
1191 W MADISON AVE 5	C	N	C	Installed after lead ban	N	Field inspection only	Y
1191 W MADISON AVE 6	C	N	C	Installed after lead ban	N	Field inspection only	Y
1230 W MADISON AVE	C	N	C	Installed after lead ban	N	Field inspection only	Y
1231 W MADISON AVE	C	N	C	Installed after lead ban	N	Field inspection only	Y
1032 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1040 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1045 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1045A W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1048 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1051 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1102 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1111 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1117 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1120 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1123 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1133 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1140 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1141 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1147 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
1150 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1153 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1159 W WASHINGTON AVE	P	N	C	Field inspection only	Y	Field inspection only	Y
1202 W WASHINGTON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1205 W WASHINGTON AVE	P	N	C	Field inspection only	Y	Field inspection only	Y
1210 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1222 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1225 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1239 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1241 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1250 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1251 W WASHINGTON AVE	P	N	C	Field inspection only	Y	Field inspection only	Y
1251 W WASHINGTON AVE	C	N	C	Installation record	N	Installation record	Y
1255 W WASHINGTON AVE	P	N	C	Field inspection only	Y	Field inspection only	Y
1271 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1274 W WASHINGTON AVE	P	N	P	Installation record	Y	Field inspection only	Y
1274 W WASHINGTON AVE	P	N	P	Installation record	Y	Field inspection only	Y
1279 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1285 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1302 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1309 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1312 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1320 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1321 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1330 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1333 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1336 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1342 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1345 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1350 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1357 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1358 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1400 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1402 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
1406 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1411 W WASHINGTON AVE	P	N	P	Installation record	N	Field inspection only	Y
1416 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1426 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1429 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1436 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1446 W WASHINGTON AVE	C	N	C	Installation record	N	Field inspection only	Y
1522 W WASHINGTON AVE	P	N	C	Field inspection only	Y	Field inspection only	Y
1536 W WASHINGTON AVE	P	N	C	Field inspection only	Y	Field inspection only	Y
1550 W WASHINGTON AVE	P	N	C	Field inspection only	Y	Field inspection only	Y
1570 W WASHINGTON AVE	P	N	C	Field inspection only	Y	Field inspection only	Y
1609 W WASHINGTON AVE	P	N	C	Field inspection only	Y	Field inspection only	Y
1620 W WASHINGTON AVE	P	N	C	Field inspection only	Y	Field inspection only	Y
1629 W WASHINGTON AVE	P	N	C	Field inspection only	Y	Field inspection only	Y
1675 W WASHINGTON AVE	P	N	DNE	Installation record	Y	Other - describe in notes	N
1344 WEBSTER LN	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1351 WEBSTER LN	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1360 WEBSTER LN	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1407 WEBSTER LN	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1410 WEBSTER LN	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1424 WEBSTER LN	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
1433 WEBSTER LN	UNK-LG	N	C	Water sampling only	N	Field inspection only	Y
745 WEBSTER ST	UNK-LG	N	C	Installation record	N	Field inspection only	Y
630 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
631 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
647 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
655 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
660 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
701 WESTVIEW ST	D.I	N	DI	Diameter > 2 inches	N	Field inspection only	Y
707 WESTVIEW ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
719 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
730 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
735 WESTVIEW ST	UNK-LG	N	P	Other - describe in notes	N	Field inspection only	Y
736 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
740 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
744 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
748 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
757 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
765 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
775 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
776 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
800 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
807 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
810 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
817 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
820 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
825 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
826 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
834 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
835 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
846 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
921 WESTVIEW ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
923 WESTVIEW ST	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
933 WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
647A WESTVIEW ST	C	N	C	Installation record	N	Field inspection only	Y
245 WHITETAIL LN	UNK-NOLG	N	C	Installed after lead ban	N	Field inspection only	Y
1090 WILLOWOOD LN	P	N	P	Field inspection only	Y	Field inspection only	Y
1101 WILLOWOOD LN	C	N	C	Installation record	N	Field inspection only	Y
1108 WILLOWOOD LN	C	N	C	Installation record	N	Field inspection only	Y
1191 WILLOWOOD LN	C	N	C	Installation record	N	Field inspection only	Y
1330 WILLOW WAY	P	N	P	Installation record	Y	Field inspection only	Y
1330 WILLOW WAY	P	N	P	Installation record	Y	Field inspection only	Y
670 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
671 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
677 WILSON AVE	C	N	DNE	Installation record	N	Other - describe in notes	N
678 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
683 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
686 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y

LOCATIONAL IDENTIFIER	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
705 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
713 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
716 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
717 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
725 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
738 WILSON AVE	UNK-LG	n	C	Other - describe in notes	N	Field inspection only	Y
745 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
750 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
759 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
769 WILSON AVE	UNK-LG	N	C	Other - describe in notes	N	Field inspection only	Y
300 WOODLAND ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
302 WOODLAND ST	C	N	C	Field inspection only	Y	Field inspection only	Y
304 WOODLAND ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
306 WOODLAND ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
308 WOODLAND ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
310 WOODLAND ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
312 WOODLAND ST	C	N	C	Installed after lead ban	N	Field inspection only	Y
314 WOODLAND ST	C	N	C	Field inspection only	Y	Field inspection only	Y
VETERANS PARK	UNK-NOLG	N	P	Other - describe in notes	N	Field inspection only	Y
PIN 03151100400800	C	N	DNE	Installation record	N	Other - describe in notes	N
PIN 03150000100402	C	N	DNE	Installation record	N	Other - describe in notes	N
PIN 03151500001100	UNK-NOLG	N	DNE	Installed after lead ban	N	Other - describe in notes	N
PIN 03151500001000	UNK-NOLG	N	DNE	Installed after lead ban	N	Other - describe in notes	N
PIN 03151500001100 #2	UNK-NOLG	N	DNE	Installed after lead ban	N	Other - describe in notes	N
PIN 03151500001200	UNK-NOLG	N	DNE	Installed after lead ban	N	Other - describe in notes	N
PIN 03158000000800	UNK-NOLG	N	DNE	Installed after lead ban	N	Other - describe in notes	N
PIN 03158000000900	UNK-NOLG	N	DNE	Installed after lead ban	N	Other - describe in notes	N
PIN 03158000001000	UNK-NOLG	N	DNE	Installed after lead ban	N	Other - describe in notes	N
PIN 03158000001100	UNK-NOLG	N	DNE	Installed after lead ban	N	Other - describe in notes	N
PIN 03158000001200	UNK-NOLG	N	DNE	Installed after lead ban	N	Other - describe in notes	N
PIN 03158000001300	UNK-NOLG	N	DNE	Installed after lead ban	N	Other - describe in notes	N
PIN 03154000100200	UNK-LG	N	DNE	Other - describe in notes	N	Other - describe in notes	N
PIN 03151500002000	C	N	DNE	Other - describe in notes	N	Installed after lead ban	N